

Vehicle Pricing Matrix - Car

Action	Cost
Touch-in	£48.00
Touch-in & Flat/Polish	£60.00
Full Mop Polish	£109.00
Touch-in Cold Metal	£51.00
Cold Metal Enhanced	£101.00
Re-align	£48.00
De-decal - (body wraps may incur an extra charge)	£91.00
Clean	£24.00
Full Valet	£48.00
Interior Trim Repair	£76.00
Door Moulding Paint	£36.00
Painted Trim	£73.00
Local Paint	£109.00
Paint	£206.00
Local Repair / Replace	£133.00
Repair / Replace – Small (1 hour repair)	£256.00
Repair / Replace – Large (2 hour repair)	£308.00
Wheel / Trim Repair / Replace	£12.00
Alloy Repair	£73.00
Windscreen Repair	£73.00
Window Switch / Boot Lock / Etc. (Inoperative)	£33.00

Replacement	Cost
Alloy Wheel Key	MRRP
Jack	MRRP
Key Volume	MRRP
Service Book	£44.00
Literature Pack	£44.00
Load Cover Volume	MRRP
Sat Nav Disc/ SD Card	MRRP
Tyre Volume	MRRP
Windscreen	MRRP

Missed Service	Cost
Service Volume - Missed 1	£211.00
Service Volume - Missed All	£666.00

Specifics for Prestige Vehicles	Cost
Tyre Prestige	MRRP
Key Prestige	MRRP
Load Cover Prestige	MRRP
Service Prestige - Missed 1	£322.00
Service Prestige - Missed All	£1,150

If you need to talk to us about possible charges, contact us on: DrivewayUKInspections@lithia.com

Vehicle Pricing Matrix - LCV / Commercial

Action	Cost
Touch-in	£48.00
Touch-in & Flat/Polish	£60.00
Full Mop Polish	£109.00
Touch-in Cold Metal	£51.00
Cold Metal Enhanced	£101.00
Re-align	£48.00
De-decal - (body wraps may incur an extra charge)	£91.00
Clean	£24.00
Full Valet	£48.00
Interior Trim Repair	£76.00
Door Moulding Paint	£36.00
Painted Trim	£73.00
Local Paint	£109.00
Paint	£206.00
Local Repair / Replace	£133.00
Repair / Replace – Small (1 hour repair)	£256.00
Repair / Replace – Large (2 hour repair)	£308.00
Wheel / Trim Repair / Replace	£12.00
Alloy Repair	£73.00
Windscreen Repair	£73.00
Window Switch / Boot Lock / Etc. (Inoperative)	£33.00

Replacement	Cost
Alloy Wheel Key	MRRP
Jack	MRRP
Key Volume	MRRP
Service Book	£44.00
Literature Pack	£44.00
Load Cover Volume	MRRP
Sat Nav Disc/ SD Card	MRRP
Tyre Volume	MRRP
Windscreen	MRRP

Missed Service	Cost
Service Volume - Missed 1	£211.00
Service Volume - Missed All	£666.00

LCV Specific Replace/Repair	Cost
Roof Small (LCV)	£393.00
Roof Large (LCV)	£581.00
Replace Roof (LCV)	£2,118.00

If you need to talk to us about possible charges, contact us on: DrivewayUKInspections@lithia.com